DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/16/2018 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER CEDARS HEALTHCARE CENTER (X4) ID SUMMARY STATEMEN PREFIX (EACH DEFICIENCY MUST TAG REGULATORY OR LSC IDE	BE PRECEDED BY FULL	B. WING ID PREFIX TAG	STREET ADDRESS, CITY, STATE, ZIP CODE 1242 CEDARS CT CHARLOTTESVILLE, VA 22903 PROVIDER'S PLAN OF CORRECTION SHOULD GEACH CORRECTIVE ACTION SHOULD GEACH	02/19/2016
CEDARS HEALTHCARE CENTER (X4) ID SUMMARY STATEMEN PREFIX (EACH DEFICIENCY MUST	BE PRECEDED BY FULL	PREFIX	1242 CEDARS CT CHARLOTTESVILLE, VA 22903 PROVIDER'S PLAN OF CORRECTION	
PREFIX (EACH DEFICIENCY MUST	BE PRECEDED BY FULL	PREFIX		
			CROSS-REFERENCED TO THE APPROF DEFICIENCY)	D BE COMPLETION
K 000 INITIAL COMMENTS			00	
An unannounced Life Safe conducted on 2/19/2016 in Code of Federal Regulation Requirements for Long Tenscope of the survey was limalife Safety Code impacts of facility was surveyed for co 2000 Life Safety Code Exister leak and subsequent repair affect on life safety. The factompliance with the Require Participation Medicare and INITIAL COMMENTS The facility is a two-story of construction. It is fully spring An unannounced Life Safety code of Federal Regulation Requirements for Long Tenscope of the survey was limalife Safety Code impacts of facility was surveyed for co 2000 Life Safety Code New and subsequent repairs has life safety. The facility was surveyed for construction and subsequent repairs has life safety. The facility was surveyed for construction and subsequent repairs has life safety. The facility was surveyed for construction.	The facility is a two-story of Type II (111) construction. It is fully sprinklered. An unannounced Life Safety Code Survey was conducted on 2/19/2016 in accordance with 42 Code of Federal Regulation, Part 483 Requirements for Long Term Care Facilities. The scope of the survey was limited to investigation of Life Safety Code impacts due to a roof leak. The facility was surveyed for compliance using the 2000 Life Safety Code New regulation. The leak and subsequent repairs had no adverse affect on life safety. The facility was found in compliance with the Requirements for Participation Medicare			(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14

days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: VA0062